Different brackets

WAB 804 01 + WAB 801 01

For further info and drawings: www.windowmaster.com/WAB804
www.windowmaster.com/WAB801

WAB 804 01 + WAB 860 01

For further info and drawings: www.windowmaster.com/WAB860
www.windowmaster.com/WAB804

WAB 805 01 + WAB 801 01

For further info and drawings: www.windowmaster.com/WAB805
www.windowmaster.com/WAB801

WAB 807 01 + WAB 801 01

For further info and drawings: www.windowmaster.com/WAB807
www.windowmaster.com/WAB801

WMX 804-n / WMX 504-n



For further info: www.windowmaster.com/WMX804



For further info: www.windowmaster.com/WMX804

1:5

Subject: WMX 804-n or WMX 504-n		Checked by:	Date: 2017-12-06 / Drawn by:
Tolerances: DS/ISO 2768-m	Material:	© WindowMaster International A/S	
WindowMaster International A/S, Skelstedet 13, 2950 Vedbæk	Tel.: 0045 45 67 03 00, Fax: 0045 45 67 03 90, info@windowmaster.dk, www.windowmaster.com	Profilesystem by	
		Client	
		Scale	Dimension MM
WindowMaster Control Systems Ltd.	Tel.: +44 1536 614070	Project	
WindowMaster GmbH	Tel.: +49 (0) 40 87409 560		
WindowMaster AG	Tel.: +41 62 289 22 22	Drawing No. LES-7110-01	

Bemærk!
Dette er kun et konstruktionsforslag til placering af motoren samt motorbeslagene. Det er til hver en tid op til den enkelte at afprøve om den givne konstruktion kan fungere i det konkrete tilfælde. Ophavsretten til denne tegning tilhører WindowMaster International A/S. Tegningen må ikke uden forudgående tilladelse fra WindowMaster International A/S kopieres videre til tredie part. Af hensyn til sikkerheden skal der monteres sikkerhedsbeslag på bundhængte vinduer.

Note!
The above illustration is merely a suggestion for positioning of the motor and the motor brackets. It is up to the installer, in each specific case, to test whether the given design will function." This drawing is the property of WindowMaster International A/S. This drawing must not, without prior permission from WindowMaster International A/S, be copied to third parties. For safety reasons, opening restrictors must be fitted on bottom-hung windows.

Achtung!
Die hier dargestellten Profile, die Positionierung der Motoren sowie deren Beschläge verstehen sich als Konstruktionsvorschlag und sind vom Anwender auf Ausführbarkeit zu prüfen. Zeichnungen mit dem Vermerk Konstruktionsvorschlag sind vom Anwender auf Richtigkeit sowie Aus- und Durchführbarkeit eigenverantwortlich zu prüfen. Die Rechte an dieser Zeichnung sind Eigentum der Firma WindowMaster International A/S. Die Zeichnung darf, auch auszugsweise, ohne unsere Genehmigung weder kopiert noch dritten Personen oder Firmen mitgeteilt werden. Aus Sicherheitsgründen müssen Fangscheren auf unten angeschlagenen Fenstern montiert werden.